

**RISK MANAGEMENT REPORT** 

ТҮРЕ	Plough - Chisel
MAKE	Gason
MODEL	17 Tyne
SERIAL NUMBER	Not visible

Report Number	OSS 20210210-1045
Date	10-Feb-2021
Created By	Geoff Gleeson
Assessor	Geoff Gleeson
Assist. Assessor(s)	
Agent	Mannes Agencies
Lot Number	23
Location	Farm 47
Assessment Purpose	Sale
State	NSW

# **TABLE OF CONTENTS**

SECTION 1	<b>IMPORTANT INFORMATION</b> Contains information outlining the scope and any limitations applicable to this Risk Management Report
SECTION 2	MACHINE DETAILS Contains standard machine specifications and details of any extras fitted
SECTION 3	<b>RISK ANALYSIS, RISK EVALUATION &amp; RISK TREATMENT</b> Contains details of the technique used to calculate risk ratings, time frame and risk treatments. Please refer to this information when reviewing and interpreting the information in section 4 & 5
SECTION 4	<b>RISK TREATMENTS REQUIRED</b> Contains detailed information regarding the risk treatments to be implemented including hazard, risk rating, time frame, relevant standards & legislative references
SECTION 5	<b>RISK TREATMENTS IN PLACE</b> Contains detailed information regarding the risk treatments in place including hazard, risk rating, relevant standards & legislative references
SECTION 6	IMAGES AND NOTES Contains images & any relevant information entered by the assessor





#### SECTION 1 IMPORTANT INFORMATION

This report generated by Plant Assessor™ © Online Safety Systems on Wednesday 10 Feb 2021 8:39 PM

This Risk Management Report has been prepared for -

(insert recipient name/company name)

This document has been prepared to cover the sale or transfer of this item of plant between the Company identified on the front cover and their named recipient. This report must not be used for any subsequent sale or transfer.

This document is provided to meet duty of care obligations as set out in relevant state and territory health and safety regulations for the supply of plant and the sale and transfer of plant.

The safety hazards associated with the operating and maintaining of this item of plant have been identified as far as practical by visual inspection. This item of plant is being sold in an "as-is" condition with known and unknown safety hazards. No physical testing has been conducted (eg. Wire rope tests, stress tests, structural/non-destructive tests, noise tests, vibration tests, brake tests, insulation tests etc.) unless stated otherwise in the notes.

This document is not intended to provide information on, nor warrant the mechanical, electrical or structural condition of this item of plant. Any information on standard features have been supplied through the manufacturer and should be used as a guide only until otherwise verified.

This item of plant should be further assessed, tested and inspected or dismantled as necessary to gauge any further hazards and /or risks relating to SPECIFIC WORKPLACE USE, which are currently unknown, in accordance with relevant standards, regulations and acts.

Under common law and relevant state and territory health and safety acts, regulations and codes of practice, there is a requirement for the plant owner, employer and operator to exercise a duty of care in the safe operation and maintenance of plant. Accordingly before this item of plant is supplied to, or used at any workplace it must be inspected to ensure it is in a fully operational, safe and serviceable condition and that operators and maintenance personnel are appropriately trained in the use & maintenance of this item of plant.

For further information regarding this report contact Online Safety Systems on 1300 72 88 52

#### SECTION 2 MACHINE DETAILS

CAPACITIES	
Capacity	
DIMENSIONS/WEIGHTS	
Width	
LINKAGE	
Linkage	
OPERATING SYSTEMS	
Cab Monitor System	
RETAIL \$	
New Price	
New Price Date	
TYRES	
Tyres	





MakeGasonModel17 TyneTypePlough - Chisel

Serial Number Assessed By Date Not visible Geoff Gleeson 10-Feb-2021

#### SECTION 3 RISK ANALYSIS / RISK EVALUATION

•	CONSEQUENCE									
A. Almost certain to	1. INSIGNIFICANT Dealt with by in house first aid	2. MINOR Treated by medical professionals, hospital out patients	3. MODERATE Significant non permanent injury overnight hospital stay	4. MAJOR Extensive permanent injury eg. Loss of fingers, extended hospital stay	5. CATASTROPHIC Death, permanent disabling injury eg. Loss of hand, quadriplegia					
A. Almost certain to occur in most circumstances	MEDIUM 8	HIGH 16	HIGH 18	CRITICAL 23	CRITICAL 25					
B. Likely to occur frequently	MEDIUM 7	MEDIUM 10	HIGH 17	HIGH 20	CRITICAL 24					
C. Possibly and likely to occur at sometime	LOW 3	MEDIUM 9	MEDIUM 12	HIGH 19	HIGH 22					
D. Unlikely to occur but could happen	LOW 2	LOW 5	MEDIUM 11	MEDIUM 14	HIGH 21					
E. May occur but only in rare circumstances	LOW 1	LOW 4	LOW 6	MEDIUM 13	MEDIUM 15					

LUATION	CRITICAL	Act immediately to mitigate risk. Implement risk treatment(s) in accordance with the risk treatment table below.		
<b>RISK EVA</b>	Act immediately to mitigate risk. Implement risk treatment(s) in accordance with the risk treatment table belo If the appropriate risk treatments are not immediately accessible establish interim risk treatment strategies. Permanent risk treatments must be implemented within one week.			
	MEDIUM	Take reasonable steps to mitigate and monitor the risk. Implement risk treatment(s) in accordance with the risk treatment table below. Permanent risk treatments must be implemented with one month.		
	LOW	Take reasonable steps to mitigate and monitor the risk. Implement risk treatment(s) in accordance with the risk treatment table below. Permanent risk treatments must be implemented with three months.		

_							
TREATMENT	Selecting the most appropriate risk treatment option involves balancing the costs and efforts of implementation against the benefits derived, with regard to legal, regulatory and other requirements. (source AS/NZS ISO 31000:2009)						
REAT	Eliminate	Eliminate the risk source.					
RISKT	Substitute	Provide an alternative that is capable of performing the same task which is safer.					
	Engineering	Provide or construct a physical barrier or guard.					
	Administration	Develop policies, procedures, practices and guidelines in consultation with employees to mitigate the risk. Provide training, instruction and supervision about the risk source.					
	Personal protective	Provide personal protective equipment to protect the individual from the risk source.					





MakeGasonModel17 TyneTypePlough - Chisel

Serial Number Assessed By Date Not visible Geoff Gleeson 10-Feb-2021

#### SECTION 4 RISK TREATMENTS REQUIRED

plant 👩

MACHINE

DETAILS

Model 17 Type

Туре

Plough - Chisel

This section of the report pertains to hazards created by use of this item of plant which currently do not have risk treatments in place. The risk treatments recommended in this section have been developed based on relevant Australian Standards, health & safety legislation, the hierarchy of risk treatment in accordance with the guidelines set forth in AS/NZS ISO 31000 – Risk Management and various other sources. The recommended risk treatment measures must be developed, implemented and validated as effective prior to the operation, maintenance or testing of this item of plant. Treatments applied must be dated and initialled adjacent the recommendations. All operators must read and understand the entire contents of this section prior to operating this item of plant.

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	Time Frame	Due Date	Date Rectified	Initial		
DELIVERY								
	HIGH 22	MEDIUM 15	1 Week	17-Feb-21				
Risk Treatment Required: SWMS Load Restraint								
Source or develop transport restraining guidelines for this r	nachine.							
Once developed, ensure that all operators follow the approved SWMS/SOP when restraining this machine for transport.								
References: Occupational Health & Safety Act & Regula	itions, Work Health & S	afety Act & Regulations	<u>;-</u>					
COMMISSIONING								
INCORRECT OPERATION	HIGH 22	MEDIUM 15	1 Week	17-Feb-21				
Risk Treatment Required: Pre-start checklist	1	1						
An operational "Pre start" checklist must be obtained for th competent in writing health and safety procedures. Once of must be rectified prior to commencement of operation. The	btained the "Pre start"	checklist must be comp	leted before each	n operation. If an	y faults are dete			
Legislation: State Health & Safety Legislation & Regulation								
References: Occupational Health & Safety Act & Regula	itions, Work Health & S	afety Act & Regulations	5-					
OPERATION								
INCORRECT OPERATION	CRITICAL 24	MEDIUM 15	Immediate	10-Feb-21				
Risk Treatment Required: Operator Competency	1	1						
Only persons who are qualified, trained and experienced ar person available for operation of this item of plant then only						etent/licensed		
Legislation: State Health & Safety Legislation & Regulation								
References: Occupational Health & Safety Act & Regula	tions, Work Health & S	afety Act & Regulations	5-					
INCORRECT OPERATION	HIGH 22	MEDIUM 15	1 Week	17-Feb-21				
Risk Treatment Required: Control Labels				<b>c</b>				
Ensure all controls including all levers, buttons, pedals, swit Once achieved these labels must be maintained in a clean of		belled as to their purpo	se and method o	f operation prior	to operating this	item of plant.		
Legislation: State Health & Safety Legislation & Regulation								
References: AS/NZS4024.1905								
CRUSHING, FALLING	HIGH 22	MEDIUM 15	1 Week	17-Feb-21				
Risk Treatment Required: No Riding On Machine	Label							
Ensure this item of plant has a hazard warning label re: "No item of plant is in operation.	o Riding on Machine", a	ttached prior to operat	ion. It must be pr	resent, clear and	legible at all time	es whilst this		
Legislation: State Health & Safety Legislation & Regulation								
References: AS1319								
Alant Make	Gason	Seria	l Number	Not visible	I			

Geoff Gleeson 10-Feb-2021

Assessed By

Date

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	Time Frame	Due Date	Date Rectified	Initial	
OPERATION							
INCORRECT OPERATION	HIGH 22	MEDIUM 15	1 Week	17-Feb-21			
Risk Treatment Required: SOP							
Source or develop Safe Operation Procedures for this item item of plant is in operation.	of plant. Once available	ensure that all opera	tors are familiar w	vith these and fol	low them at all ti	mes whilst this	
References: Occupational Health & Safety Act & Regula	tions, Work Health & S	afety Act & Regulatior	1S-				
INCORRECT OPERATION	HIGH 22	MEDIUM 15	1 Week	17-Feb-21			
Risk Treatment Required: Operation Handbook							
The manufacturer's operation handbook is not available for This handbook must be sourced and made available to all c cannot be sourced the operation manual must be develope handbook prior to operating. Legislation: State Health & Safety Legislation & Regulation	operators and maintena	nce staff at all times a	is a requirement o	of current legislati	ion. If Operation		
References: Occupational Health & Safety Act & Regula	itions, Work Health & Sa	afety Act & Regulatior	IS-				
FIRE	HIGH 21	MEDIUM 15	1 Week	17-Feb-21			
Risk Treatment Required: Fire Extinguisher No fire extinguishers are installed on this item of plant. Fire readily accessible to the operator. Regular inspections must Legislation: State Health & Safety Legislation & Regulation						ley must be	
References:							
INCORRECT OPERATION	HIGH 21	MEDIUM 15	1 Week	17-Feb-21			
Risk Treatment Required: Tow Point This item of plant does not have a clear towing instruction when towing this item of plant. Once attached this instructi Legislation: State Health & Safety Legislation & Regulation				se instructions m	ust be adhered t	o at all times	
References: Occupational Health & Safety Act & Regula	tions, Work Health & Sa	afety Act & Regulatior	IS-				
DESIGN COMPLIANCE							
COLLISION, CRUSHING, OPERATIONAL MALFUNCTION	HIGH 22	MEDIUM 15	1 Week	17-Feb-21			
<b>Risk Treatment Required:</b> Transit Locking Device This item of plant does not have fully functional locking devinstruction label adjacent must be present at all times.		ng transit. These must	be installed and u	used whenever th	ne machine is in t	transit. A clear	
Legislation: State Health & Safety Legislation & Regulation References: ISO31000							
INCORRECT OPERATION	HIGH 20	MEDIUM 14	1 Week	17-Feb-21			
<b>Risk Treatment Required:</b> Intuitive Controls The controls fitted to this item of plant must be orientated so that the movement of the control is consistent with the action of the machine e.g. moving a control lever to the left results in the machine turning to the left.							
Once achieved this design feature must be maintained at al	Il times whilst this item	of plant is in operatio	n.				
References: AS/NZS4024.1906							
DETAILS Model	Gason 17 Tyne Plough - Chisel		ial Number essed By e	Not visible Geoff Gleeson 10-Feb-2021		Page 5 of 7	

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	Time Frame	Due Date	Date Rectified	Initial
DESIGN COMPLIANCE						
SLIPPING	HIGH 17	LOW 6	1 Week	17-Feb-21		
Risk Treatment Required: Control Levers/Pedals	Buttons					
Ensure all controls including all levers, buttons, pedals, swit maintained to this level at all times whilst operating this iter		and free from damage p	prior to operating	g this item of plan	it. These conditio	ns must be
_egislation: State Health & Safety Legislation & Regulation						
References: AS/NZS4024.1901						
MAINTENANCE						
<b>BURNS, STRIKING</b>	HIGH 22	MEDIUM 15	1 Week	17-Feb-21		
Risk Treatment Required: Hydraulic Damage						
The hydraulic hoses to this item of plant must be free from hoses or protection must be installed as per the time frame operation. Inspection of the hoses and protection should be	above. Once installed,	ensure that hoses and	protection are in	n place at all time		
egislation: State Health & Safety Legislation & Regulation						
References: AS2671, AS4024, ISO4413						
Assessor Comments: Ensure that all hydraulic hoses a operation.	are inspected by a com	petent person and any	damaged hoses	are replaced and	secured correctly	/ prior to
INCORRECT OPERATION	HIGH 22	MEDIUM 15	1 Week	17-Feb-21		
Risk Treatment Required: Maintenance Manual						
The manufacturer's maintenance manual(s) are not availab	e for this item of plant					
These manuals must be sourced and made freely available						e manuals
Lannot de sourceu, the maintenance manual(s) must de de						
Legislation: State Health & Safety Legislation & Regulation	tions, Work Health & S	afety Act & Regulations	-			
cannot be sourced, the maintenance manual(s) must be de Legislation: State Health & Safety Legislation & Regulation <b>References:</b> Occupational Health & Safety Act & Regula OPERATIONAL MALFUNCTION	tions, Work Health & S HIGH 21	afety Act & Regulations MEDIUM 15	- 1 Week	17-Feb-21		
egislation: State Health & Safety Legislation & Regulation References: Occupational Health & Safety Act & Regula OPERATIONAL MALFUNCTION				17-Feb-21		
Legislation: State Health & Safety Legislation & Regulation References: Occupational Health & Safety Act & Regula OPERATIONAL MALFUNCTION	HIGH 21			17-Feb-21		
Legislation: State Health & Safety Legislation & Regulation         References:       Occupational Health & Safety Act & Regula         Image: Operational Malfunction         Risk Treatment Required:       Service Records	HIGH 21 tem of plant. this item of plant. Servections re: the general	MEDIUM 15 rice and maintenance re condition of the item of	1 Week	eveloped and ma (but not limited to	<ul> <li>b) tyre condition,</li> </ul>	oil levels and
Legislation: State Health & Safety Legislation & Regulation References: Occupational Health & Safety Act & Regula OPERATIONAL MALFUNCTION Risk Treatment Required: Service Records Service and maintenance records are not available for this is this risk assessment will form the basis of your records for safety management programme. This includes regular inspe- wear and tear on critical items such as brakes and steering,	HIGH 21 tem of plant. this item of plant. Servections re: the general	MEDIUM 15 rice and maintenance re condition of the item of	1 Week	eveloped and ma (but not limited to	<ul> <li>b) tyre condition,</li> </ul>	oil levels and

### SECTION 5 RISK TREATMENTS IN PLACE

This section of the report pertains to risk treatments currently in place on this item of plant. This section must be read in conjunction with the safety section of the manufacturers handbook. All operators must read and understand the entire contents of this section prior to operating this item of plant. These treatments or equivalent must remain in place at all times whilst this item of plant is in operation.

HAZARD(S)	F	Prelim. Risk Rating	<b>Residual Risk Rating</b>
DESIGN COMPLIANCE			
BURNS, STRIKING		HIGH 22	MEDIUM 15
Risk Treatment In Place: Hydraulic Hoses			
Plant MACHINE Make Gason Model 17 Tyne	Serial Number	Not visible Geoff Gleeson	
Assessor DETAILS Model 17 Tyne Type Plough - Chisel	Assessed By Date	10-Feb-2021	Page 6 of

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating						
DESIGN COMPLIANCE								
This item of plant has hydraulic hoses. These hoses must be inspected each day or before each use for wear and tear. If there are visible signs of wear immediate action must be taken to control the risk arising from this wear. These inspections must be documented.								
Hydraulic fluid at high pressure can penetrate the skin, never use any part of your body to check for leaks. If Always use a piece of cardboard or similar to check for suspected leaks.	oil penetrates the skin seek me	dical advice immediately.						
Hydraulic pressure can be stored and is a hazard. Before disconnection or connection of hydraulic hoses complete the following steps -								
<ol> <li>Stop engine</li> <li>Keep all bystanders clear of the work area</li> <li>Refer to operators manual as to methods to release pressure</li> <li>Wait 5 minutes</li> </ol>								
References: AS2671, AS4024								
STRAINS	HIGH 19	LOW 5						
Risk Treatment In Place: Controls Ergonomics								
All controls including all levers, buttons, pedals, switches etc, are placed near the operator work position and operator's normal duties. This applies for all persons within the 95th percentile of the normal population distri		during the execution of the						
References: AS/NZS4024.1901								
OPERATIONAL MALFUNCTION	HIGH 22	LOW 2						
Risk Treatment In Place: Plant Modification								
The plant is in original condition.								
References:								
MAINTENANCE								
COLLISION, INSTABILITY	HIGH 22	MEDIUM 15						
Risk Treatment In Place: Tyres								
The tyres and wheel components must be inspected as part of a "pre start" checklist. These inspections must	be documented as part of your	plant safety programme.						
References: ISO31000								
CURRENT OR PREVIOUS STRUCTURAL DAMAGE	CRITICAL 25	MEDIUM 15						
Risk Treatment In Place: Structural Integrity								
Regular checks for structural damage must be undertaken. Look for cracks in frames/chassis (current or repaired), bends or damage to structural components, etc.								
References:								
OPERATIONAL MALFUNCTION	HIGH 22	LOW 2						
Risk Treatment In Place: Major Fluid Leaks								
This item of plant must remain free from leaks at all times whilst in operation (this includes engine, transmiss and hydraulics). Development of a major leak will require this item of plant to be stood-down until repaired. N								
References: ISO31000								

## SECTION 6 IMAGES AND NOTES







ТҮРЕ	Plough - Chisel	Report Number	OSS 20210210-1045
MAKE	Gason	Date	10-Feb-2021
MODEL	17 Tyne	Created By	Geoff Gleeson
SERIAL NUMBER	Not visible	Assessor	Geoff Gleeson
		Assist. Assessor(s)	
		Agent	Mannes Agencies
		Lot Number	23
		Location	Farm 47
		Assessment Purpose	Sale
		State	NSW

# PURCHASER ACKNOWLEDGEMENT

I the undersigned acknowledge that I have read and understand the risk management report described above. I also acknowledge that I have received a copy of this risk management report. I also acknowledge that I am authorised to sign on behalf of the purchaser.

Name	
Company Name	
Position	
Signature	
Date	

The manufacturer's operational & maintenance handbooks have been supplied, (circle one) YES NO (initial) \_\_\_\_\_

Please transfer this assessment to my Plant Assessor membership as a (circle one) HIRE / PLANT IN USE asessment. My Plant Assessor username is \_\_\_\_\_



Wednesday, 10 Feb 2021 08:39 PM



MakeGasonModel17 TyneTypePlough - Chisel

Serial Number Assessed By Date Not visible Geoff Gleeson 10-Feb-2021