

TVDE

Lot Number

Assessment Purpose

Location

State

RISK MANAGEMENT REPORT

TIPE	i ractor - Rigid	
MAKE	International	
MODEL	686	
SERIAL NUMBER	2510130A001246	
Report Number	OSS 20210209-1448	
Date	9-Feb-2021	
Created By	Geoff Gleeson	
Assessor	Geoff Gleeson	
Assist. Assessor(s)		
Agent	Mannes Agencies	

TABLE OF CONTENTS

06

Sale

NSW

Farm 4003

SECTION 1	IMPORTANT INFORMATION

Contains information outlining the scope and any limitations applicable to this Risk Management Report

SECTION 2 MACHINE DETAILS

Contains standard machine specifications and details of any extras fitted

RISK ANALYSIS, RISK EVALUATION & RISK TREATMENT

SECTION 3 Contains details of the technique used to calculate risk ratings, time frame and risk treatments. Please refer to this information when reviewing and interpreting the information in section 4 & 5

RISK TREATMENTS REQUIRED

Tractor Digid

Contains detailed information regarding the risk treatments to be implemented including hazard, risk rating, time frame, relevant standards & legislative references

RISK TREATMENTS IN PLACE

Contains detailed information regarding the risk treatments in place including hazard, risk rating, relevant standards & legislative references

IMAGES AND NOTES

Contains images & any relevant information entered by the assessor



SECTION 5

SECTION 6



SECTION 1 IMPORTANT INFORMATION

This report generated by Plant Assessor™ © Online Safety Systems on Wednesday 10 Feb 2021 8:41 PM

This Risk Management Report has been prepared for -

(insert recipient name/company name)

This document has been prepared to cover the sale or transfer of this item of plant between the Company identified on the front cover and their named recipient. This report must not be used for any subsequent sale or transfer.

This document is provided to meet duty of care obligations as set out in relevant state and territory health and safety regulations for the supply of plant and the sale and transfer of plant.

The safety hazards associated with the operating and maintaining of this item of plant have been identified as far as practical by visual inspection. This item of plant is being sold in an "as-is" condition with known and unknown safety hazards. No physical testing has been conducted (eg. Wire rope tests, stress tests, structural/non-destructive tests, noise tests, vibration tests, brake tests, insulation tests etc.) unless stated otherwise in the notes.

This document is not intended to provide information on, nor warrant the mechanical, electrical or structural condition of this item of plant. Any information on standard features have been supplied through the manufacturer and should be used as a guide only until otherwise verified.

This item of plant should be further assessed, tested and inspected or dismantled as necessary to gauge any further hazards and /or risks relating to SPECIFIC WORKPLACE USE, which are currently unknown, in accordance with relevant standards, regulations and acts.

Under common law and relevant state and territory health and safety acts, regulations and codes of practice, there is a requirement for the plant owner, employer and operator to exercise a duty of care in the safe operation and maintenance of plant. Accordingly before this item of plant is supplied to, or used at any workplace it must be inspected to ensure it is in a fully operational, safe and serviceable condition and that operators and maintenance personnel are appropriately trained in the use & maintenance of this item of plant.

For further information regarding this report contact Online Safety Systems on 1300 72 88 52

SECTION 2 MACHINE DETAILS

- NOISE TEST RESULTS					
1. Manufacturers specified noise level dBA					
2. Ambient noise level dBA					
3. Noise level - Operator position (high idle) dBA					
4. Noise level - Operator position (low idle) dBA					
5. Noise level LHS dBA @ m (high idle)					
6. Noise level Front dBA @ m (high idle)					
7. Noise level RHS dBA @ m (high idle)					
8. Noise level Rear dBA @ m (high idle)					
3PL					
3PL	Std/				
3PL Category	II				
3PL Draft Sensing					
3PL Lift Kg @ Position					
BRAKES					
Brake Type	Wet disc				
DIMENSIONS/WEIGHTS	·				
Dry Weight (kg) 3524					
Max Operating Weight (kg)					
Make International	Serial Number	2510130A001246			





DIMENSIONS/WEIGHTS	
Min width (mm)	2270
Turning Circle (mm - no brakes)	
Weight (kgs)	3524
DRIVES	
Drive Configuration	2wd
ENGINE	
Engine Hours	
Engine Make & Model	International D310
Engine No Cylinders/Cc	6cyl x 5.0L (310cu")
Engine Number	
Engine Power kW/(Hp)	57kW 76hp
Max torque	
Power rating RPM	2000
EXTRAS	
A/C	No/
Front Linkage	No/
Remotes Standard/Max	
ROPS Cab	
ROPS Frame Only	
GENERAL	
Electronic Monitor - Engine Functions	
Electronic Monitor - Hectares/Hour	
Electronic Monitor - Wheel Slip	
Max torque (Nm at RPM)	
Odometer	
Power rating standard	
HYDRAULICS	
Hydraulic Pump Type	
Hydraulic System	
Hydraulics Max Pressure	
РТО	
Front PTO	No/
Mid PTO	No/
PTO ground speed / 540E	,
PTO kw/(hp)	49kW (66hp)
PTO rating source	
PTO speed selection method	
PTO speeds	540
PTO speeds 2	
PTO type	Independent
Rear PTO	Std/
RETAIL \$	
New Price	
New Price Date	
SAFETY STRUCTURES	<u> </u>
FOPS Serial No.	
ROPS Serial No.	
STEERING	'
Steering Type	Power assist
TRANSMISSION	, orrei dobbe
Clutch	10/2
Gears Fwd/Rev High-Low/Shuttle	10/2 Yes/
Speed Min To Max	2.9-26.4 km/h
opeca i iii i o i iux	Torque Amplifier





TRANSMISSION	
Transmission Type	Power shift
TYRES	
Standard Front Tyre Size	7.50-16
Standard Rear Tyre Size	15.5-38
Turf Front Tyres	
Turf Rear Tyres	
EXTRAS	
3 PTL	
Drawbar	
Fork attachment	
PTO - Rear	
Rear Remotes	
Rear wheel weights	





RIS	SK ANALYSIS									
		CONSEQUENCE								
doop		1. INSIGNIFICANT Dealt with by in house first aid	2. MINOR Treated by medical professionals, hospital out patients	3. MODERATE Significant non permanent injury overnight hospital stay	4. MAJOR Extensive permanent injury eg. Loss of fingers, extended hospital stay	5. CATASTROPHIC Death, permanent disabling injury eg. Loss of hand, quadriplegia				
- LIKELIHOOD	A. Almost certain to occur in most circumstances	MEDIUM 8	HIGH 16	HIGH 18	CRITICAL 23	CRITICAL 25				
•	B. Likely to occur frequently	MEDIUM 7	MEDIUM 10	HIGH 17	HIGH 20	CRITICAL 24				
	C. Possibly and likely to occur at sometime	LOW 3	MEDIUM 9	MEDIUM 12	HIGH 19	HIGH 22				
	D. Unlikely to occur but could happen	LOW 2	LOW 5	MEDIUM 11	MEDIUM 14	HIGH 21				
	E. May occur but only in rare circumstances	LOW 1	LOW 4	LOW 6	MEDIUM 13	MEDIUM 15				

LUATION	CRITICAL	Act immediately to mitigate risk. Implement risk treatment(s) in accordance with the risk treatment table below.
RISK EVA	HIGH	Act immediately to mitigate risk. Implement risk treatment(s) in accordance with the risk treatment table below. If the appropriate risk treatments are not immediately accessible establish interim risk treatment strategies. Permanent risk treatments must be implemented within one week.
	MEDIUM	Take reasonable steps to mitigate and monitor the risk. Implement risk treatment(s) in accordance with the risk treatment table below. Permanent risk treatments must be implemented with one month.
	LOW	Take reasonable steps to mitigate and monitor the risk. Implement risk treatment(s) in accordance with the risk treatment table below. Permanent risk treatments must be implemented with three months.

RISKTREATMENT	Selecting the most appropriate risk treatment option involves balancing the costs and efforts of implementation against the benefits derived, with regard to legal, regulatory and other requirements. (SOUTCE AS/NZS ISO 31000:2009)					
	Eliminate	Eliminate the risk source.				
	Substitute	Provide an alternative that is capable of performing the same task which is safer.				
	Engineering	Provide or construct a physical barrier or guard.				
	Administration	Develop policies, procedures, practices and guidelines in consultation with employees to mitigate the risk. Provide training, instruction and supervision about the risk source.				
	Personal protective	Provide personal protective equipment to protect the individual from the risk source.				





SECTION 4 RISK TREATMENTS REQUIRED

This section of the report pertains to hazards created by use of this item of plant which currently do not have risk treatments in place. The risk treatments recommended in this section have been developed based on relevant Australian Standards, health & safety legislation, the hierarchy of risk treatment in accordance with the guidelines set forth in AS/NZS ISO 31000 – Risk Management and various other sources. The recommended risk treatment measures must be developed, implemented and validated as effective prior to the operation, maintenance or testing of this item of plant. Treatments applied must be dated and initialled adjacent the recommendations. All operators must read and understand the entire contents of this section prior to operating this item of plant.

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	Time Frame	Due Date	Date Rectified	Initial
DELIVERY						
CRUSHING	HIGH 22	MEDIUM 15	1 Week	16-Feb-21		

Risk Treatment Required: SWMS Loading/Unloading

Source or develop guidelines for loading and unloading this machine to and from a flat top truck or trailer, low loader or tilt tray.

Once developed, ensure that all operators follow approved SWMS/SOP when loading and unloading this machine to and from a flat top truck or trailer, low loader or tilt tray.

References: Occupational Health & Safety Act & Regulations, Work Health & Safety Act & Regulations-



Risk Treatment Required: SWMS Load Restraint

Source or develop transport restraining guidelines for this machine.

Once developed, ensure that all operators follow the approved SWMS/SOP when restraining this machine for transport.

References: Occupational Health & Safety Act & Regulations, Work Health & Safety Act & Regulations-

OPERATION

INCORRECT OPERATION	CRITICAL 24	MEDIUM 15	Immediate	09-Feb-21				

Risk Treatment Required: Operator Competency

Only persons who are qualified, trained and experienced and/or hold the relevant certification/license can operate this item of plant. If there is not a competent/licensed person available for operation of this item of plant then only persons who are supervised by a competent/licensed person can operate this item of plant.

Legislation: State Health & Safety Legislation & Regulation

References: Occupational Health & Safety Act & Regulations, Work Health & Safety Act & Regulations-

ELECTROCUTION HIGH 22 MEDIUM 15 1 Week 16-Feb-21

Risk Treatment Required: Electrical Approach Distances

Attach a clear hazard warning label re: overhead electrical hazards and minimum approach distances adjacent operator work areas and any access to the top of the item of plant. These distances must be adhered to strictly. Once fitted these labels and tables must be present, clear and legible at all times.

Spotters are required when working within 5 metres of the minimum approach distance of any live electrical apparatus.

Any encroach within the minimum approach distances must only occur if the following provisions have been met -

- 1. The machine is designed to work within the minimum approach distances
- 2. Permission has been granted by the electricity company
- 3. Safe systems of work have been documented and approved

Legislation: State Health & Safety Legislation & Regulation

References: ISO31000

INCORRECT OPERATION	HIGH 22	MEDIUM 15	1 Week	16-Feb-21	

Risk Treatment Required: Control Labels

Ensure all controls including all levers, buttons, pedals, switches etc. are clearly labelled as to their purpose and method of operation prior to operating this item of plant. Once achieved these labels must be maintained in a clean condition at all times.

Legislation: State Health & Safety Legislation & Regulation

References: AS/NZS4024.1905





HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	Time Frame	Due Date	Date Rectified	Initial		
OPERATION				<u> </u>				
CRUSHING, FALLING	HIGH 22	MEDIUM 15	1 Week	16-Feb-21				
tisk Treatment Required: Passenger Seat Label name that a clear hazard warning label re: Operator only, once fitted this label must be clear and legible at all times watercrees: AS1319-			f this item of pla	nt. Passengers m	oust not be carrie	d at anytime.		
INCORRECT OPERATION	HIGH 22	HIGH 21	1 Week	16-Feb-21				
isk Treatment Required: Intended Purpose Statensure that all operators and maintenance persons are farm		urers intended purpose	for this tractor.					
ractors in general are designed predominately for use in a ource from the rear.	griculture, forresty and	I community work. The	main functions i	nclude - to pull, c	arry, push or pro	vide a power		
I usage must be within the tractors stated capacities. Ope	eration and attempted o	operation outside these	capacities is con	sidered incorrect	usage.			
l alterations/modifications must be approved by the manu	ıfacturer e.g. attachme	nts such as loaders.						
e aware that there may be authorities which have restricti	ons on the usage of th	is tractor in certain envi	ronments e.g ro	ad authorities.				
deferences: AS/NZS2153.3, Occupational Health & Safe	ety Act & Regulations, \	Work Health & Safety Ad	t & Regulations	-				
ENTANGLEMENT	HIGH 22	HIGH 21	1 Week	16-Feb-21				
Risk Treatment Required: PTO Mastershield Label Ensure that the PTO (Power Take Off) outlet(s) or PIC (Power Input Connection) connection(s) on this item of plant have clear and legible hazard warning label(s) fitted. Once fitted this label(s) must be in place at all times whilst this item of plant is in operation.								
egislation: State Health and Safety Legislation and Regular eferences: AS1121	tion							
INCORRECT OPERATION, OPERATIONAL MALFUNCTION	HIGH 22	MEDIUM 15	1 Week	16-Feb-21				
isk Treatment Required: Drawbar Capacity Laborators that the rear of this item of plant has a hazard warmoust be present and fully functional and serviceable at all to	ing label adjacent the	drawbar/tow hitch re: m	naximum towing	capacity, crushin	g, keep clear. Or	ice installed i		
egislation: State Health & Safety Legislation & Regulation								
eferences: ISO31000								
BURNS, EXPLOSION, POISONING	HIGH 22	MEDIUM 15	1 Week	16-Feb-21				
tisk Treatment Required: Tank ID Label insure the tank(s) on this item of plant have clear, legible I hese must be present, clear and legible at all times. (this in				sary controls re:	the contents. On	ce attached		
egislation: State Health & Safety Legislation & Regulation	, ,, ,, ,		-,					
eferences: Occupational Health & Safety Act & Regula	tions, Work Health & S	afety Act & Regulations	_					
INCORRECT OPERATION	HIGH 22	MEDIUM 15	1 Week	16-Feb-21				
isk Treatment Required: Pre-op Checklist Tracto								
ource or develop pre-operational checklist for this Tractor eferences: Occupational Health & Safety Act & Regula	• •		•	section of Plant A	Assessor)			
INCORRECT OPERATION	HIGH 22	MEDIUM 15	1 Week	16-Feb-21				
Lisk Treatment Required: SOP Tractor								
•	or (Safe Operation Pro	ocedures are available v	a the Custom D	enorts section of	Dlant Accessor)			
ource or develop Safe Operation Procedures for this Tract	or (Saic Operation Fre	occurres are available v	a the Custom Re	cports acction of	Flailt Assessoi)			





Make International
Model 686
Type Tractor - Rigid

Serial Number Assessed By Date

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	Time Frame	Due Date	Date Rectified	Initial		
OPERATION								
INCORRECT OPERATION	HIGH 22	MEDIUM 15	1 Week	16-Feb-21				

Risk Treatment Required: Operation Handbook

The manufacturer's operation handbook is not available for this item of plant. A full assessment of the competence of operators must also be undertaken.

This handbook must be sourced and made available to all operators and maintenance staff at all times as a requirement of current legislation. If Operation handbook cannot be sourced the operation manual must be developed by a competent person. All personnel who may operate this item of plant must read and be familiar with this handbook prior to operating.

Legislation: State Health & Safety Legislation & Regulation

References: Occupational Health & Safety Act & Regulations, Work Health & Safety Act & Regulations-

CRUSHING HIGH 22 MEDIUM 15 1 Week 16-Feb-21

Risk Treatment Required: ROPS seat belt label

This item of plant is fitted with a ROPS, ensure an advisory label stating that "seatbelts must be worn" is fitted.

Once fitted this label must be present, clean and legible at all times

All operators and passengers must wear seatbelts whilst on this item of plant.

References: AS1636



Risk Treatment Required: Phone Use label

This item of plant must be fitted with an instruction label advising that mobile phones must not be used whilst operating this machine. Accordingly all operators must not use a mobile phone at any time whilst operating machine. If phone use is necessary then operator must place machine in park configuration in a safe position prior to phone use. Operators MUST adhere to this advice at all times.

Once fitted this label must be clear and legible at all times whilst this item of plant is in operation.

References: AS1319-, ISO31000



CRUSHING HIGH 21 MEDIUM 15 1 Week 16-Feb-21

Risk Treatment Required: 3PL Crush Zone Label

Ensure that the rear of this item of plant has a hazard warning label adjacent the 3PL (three point linkage) area re: crushing, keep clear. Once installed it must be present and fully functional and serviceable at all times.

Legislation: State Health & Safety Legislation & Regulation

References: AS/NZS2153.3

FIRE	HIGH 21	MEDIUM 15	1 Week	16-Feb-21		
------	---------	-----------	--------	-----------	--	--

Risk Treatment Required: Fire Extinguisher

No fire extinguishers are installed on this item of plant. Fire extinguisher(s) to AS 1841 must be present and fully functional and serviceable at all times. They must be readily accessible to the operator. Regular inspections must also be carried out in accordance with the manufacturer's requirements and AS 1851

Legislation: State Health & Safety Legislation & Regulation

References:



Risk Treatment Required: Hearing Protection Label - Operator

Prior to operating this item of plant a sound pressure level test must be conducted at the operator work area. If SPL > 85 dB(A) then hazard warning labels re: wearing of hearing protection must be attached. Tools and small items of plant require as large a label as practicable, all other items of plant must have a 50mm label to the operator's console. Once attached these labels must be present, clear and legible at all times whilst this item of plant is in operation.

Legislation: State Health & Safety Legislation & Regulation

References: AS/NZS1269, AS3781-





Prelim. Risk **Residual Risk Time Date** Initial HAZARD(S) **Due Date** Rectified **Rating Rating** Frame **OPERATION CRUSHING** MEDIUM 15 MEDIUM 15 1 Month 11-Mar-21

Risk Treatment Required: ROPS Label

Attach hazard warning label stating that the ROPS must not be damaged at any time (including cuts, drill holes and welds). This label must be present, clean and legible at all times.

Legislation: State Health & Safety Legislation & Regulation

References: AS1636



Risk Treatment Required: Engine Guard Label

Ensure all engine guards have a hazard warning label which states that the guard must not be opened unless the engine is not running and all moving parts behind have stopped. These labels must be present and fully functional and serviceable at all times whilst this item of plant is in operation.

Legislation: State Health & Safety Legislation & Regulation

References: AS/NZS4024.1201, AS1319-



Risk Treatment Required: Warning Device (horn)

Ensure that this item of plant is fitted with a fully functional audible warning device such as a horn. Once installed this must be easily accessed by the operator, and easily identifiable by nearby pedestrians.

Once installed, Operators should ensure the warning devices are functional at the start if each shift, by completing pre-start checklists. Warning devices should operate automatically where appropriate (eg reversing)

Legislation: State Health & Safety Legislation & Regulation

References: AS/NZS2153, ISO7731



Risk Treatment Required: Recovery Point Label

Ensure that this item of plant is fitted with a hazard warning label adjacent the recovery tow point which states "Recovery tow point – Read manufacturer's towing instructions before towing". Failure to do so could result in DEATH or SERIOUS INJURY.

Once fitted this label must be clear and legible at all times whilst this item of plant is in operation.

References: ISO31000

DESIGN COMPLIANCE

STOP ENTANGLEMENT	CRITICAL 24	MEDIUM 15	Immediate	09-Feb-21		
-------------------	-------------	-----------	-----------	-----------	--	--

Risk Treatment Required: PTO Mastershield

Ensure that the PTO (Power Take Off) outlet(s) or PIC (Power Input Connection) connection(s) on this item of plant are guarded. Once fitted this guard(s) must be in place at all times whilst this item of plant is in operation.

Legislation: State Health and Safety Legislation and Regulation

References: AS1121



Risk Treatment Required: Beacon

A 55 watt amber rotating safety beacon or strobe light must be fitted to this item of plant prior to operation which meets the following criteria during normal daylight -

- Is visible up to 200m in all directions (allowing for intermittent obstruction from the plant structure whilst the plant is in operation)
- Is fitted in the most appropriate location on machine to maximise visibility without risking continual damage

NOTE: more than one beacon may need to be fitted to meet these criteria

Once fitted this beacon must be fully functional at all times whilst the item of plant is in operation

Legislation: State Health & Safety Legislation & Regulation

References: AS/NZS4024.1201





Make International
Model 686
Type Tractor - Rigid

Serial Number Assessed By Date

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	Time Frame	Due Date	Date Rectified	Initial	
DESIGN COMPLIANCE							
ROPS CRUSHING	HIGH 22	MEDIUM 15	1 Week	16-Feb-21			

Risk Treatment Required: Ag ROPS

Ensure a Rollover Protective Structure (ROPS) to AS 1636 is fitted to this item of plant prior to operation. A permanent label stating this standard must be attached to the structure. It must also carry a warning label re: wearing of seat belts whilst operating this item of plant.

Legislation: State Health & Safety Legislation & Regulation

References: AS1636



COLLISION, CRUSHING HIGH 22 MEDIUM 15 1 Week 16-Feb-21

Risk Treatment Required: Loose Items - Operator Work Area

Ensure all items that could cause harm to the operator in the event of a collision or rollover are securely restrained.

References: ISO31000

CRUSHING	HIGH 22	MEDIUM 15	1 Week	16-Feb-21

Risk Treatment Required: Seat Belt

Ensure that this item of plant is fitted with an operator seat belt which is free from damage, and permanently and sturdily attached. Once fitted operators must use this seat belt at all times during operation.

References: ISO3776.1



ENTANGLEMENT HIGH 22 MEDIUM 15 1 Week 16-Feb-21

Risk Treatment Required: Engine Guards

Ensure the engine fan, alternator belts, pulleys and gears are guarded. These guards must be present and fully functional and serviceable at all times whilst this item of plant is in operation.

Legislation: State Health & Safety Legislation & Regulation

References: AS/NZS4024.1601



OPERATIONAL MALFUNCTIONHIGH 22LOW 21 Week16-Feb-21

Risk Treatment Required: Plant Modification

The assessor has indicated that this item of plant has had some form of modification. Details of this are contained in the notes section at the rear of this report. Modifications must be added to and monitored as part of the start up check list and maintenance programme.

Legislation: State Health & Safety Legislation & Regulation

References:

Assessor Comments:

Fitted with Forklift attachment at rear, ensure all operators are trained and competent prior to use. Ensure SWL for attachment is not exceeded and that SWL and crush zone labels are fitted prior to use.



COLLISION, CRUSHING, ENTANGLEMENT, STRIKING

HIGH 22

MEDIUM 15

1 Week

16-Feb-21

Risk Treatment Required: Neutral Start

This item of plant does not have a neutral start control in place. Ensure that a neutral start control is in place prior to operating this item of plant.

Once fitted it must be fully functional and serviceable at all times whilst this item of plant is in operation.

Legislation: State Health & Safety Legislation & Regulation

References: AS4024.1603



INCORRECT OPERATION	HIGH 20	MEDIUM 14	1 Week	16-Feb-21	
---------------------	---------	-----------	--------	-----------	--

Risk Treatment Required: Intuitive Controls

The controls fitted to this item of plant must be orientated so that the movement of the control is consistent with the action of the machine e.g. moving a control lever to the left results in the machine turning to the left.

Once achieved this design feature must be maintained at all times whilst this item of plant is in operation.

References: AS/NZS4024.1906





Prelim. Risk **Residual Risk** Time **Date** Initial HAZARD(S) **Due Date** Rectified Rating **Rating Frame DESIGN COMPLIANCE** INCORRECT OPERATION, HIGH 17 LOW 6 1 Week 16-Feb-21 **SLIPPING**

Risk Treatment Required: Control Levers/Pedals/Buttons

Ensure all controls including all levers, buttons, pedals, switches etc. are non-slip and free from damage prior to operating this item of plant. These conditions must be maintained to this level at all times whilst operating this item of plant.

Legislation: State Health & Safety Legislation & Regulation

References: AS/NZS4024.1901

If you carry He my interes I CAN'T SEE YOU TO BE TO	MEDIUM 12	MEDIUM 11	1 Month	11-Mar-21		
---	-----------	-----------	---------	-----------	--	--

Risk Treatment Required: Operator Mirrors

At least two (2) operator rear view mirrors must be fitted to this item of plant prior to operation. These mirrors must be ergonomically placed to enable the operator clear view around the item of plant. Once fitted they must be fully functional and correctly maintained at all times. There must always be at least one mirror on each side to provide rear vision to the operator to avoid striking bystanders and objects.

Legislation: State Health & Safety Legislation & Regulation.

References: AS/NZS2153, AS/NZS4024.1201



Risk Treatment Required: Battery Cover

Ensure that all batteries fitted to this item of plant constrained to prevent displacement & fitted with a permanent sturdy cover which allows for ventilation.

Once achieved the constraint and cover must be present, fully functional and serviceable at all times whilst this item of plant is in operation.

Legislation: State Health & Safety Legislation & Regulation

References: AS/NZS4024.1201



FALLING, SLIPPING

MEDIUM 12

LOW 6

1 Month

11-Mar-21

Risk Treatment Required: Access/Egress Instruction Label

Ensure the access and egress to the cabin/work area has an instruction label fitted with the following information as a minimum -

All personnel must -

- 1. Always face the item of plant during access and egress.
- 2. Always maintain three points of contact during access and egress.
- 3.Ensure the steps are clean.
- 4. Never jump off machine.

Once fitted this label must be clear and legible at all times whilst this item of plant is in operation.

References: ISO31000, ISO4252

MAINTENANCE



Risk Treatment Required: Brakes

The brakes fitted to this item of plant must be fully functional at all times whilst this item of plant is in operation. The brakes on this item of plant require remedial action before operating this machine. The brakes must be regularly inspected and tested. These inspections and tests must be documented as part of your plant safety programme.

Legislation: State Health & Safety Legislation & Regulation

References: AS/NZS2153

Assessor Comments: Brakes must be tested prior to use.





HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	Time Frame	Due Date	Date Rectified	Initial
MAINTENANCE						
BURNS, STRIKING	HIGH 22	MEDIUM 15	1 Week	16-Feb-21		

Risk Treatment Required: Hydraulic Damage

The hydraulic hoses to this item of plant must be free from damage and have protection against damage arising from contact with the plant structure. Replacement hoses or protection must be installed as per the time frame above. Once installed, ensure that hoses and protection are in place at all times whilst this item of plant is in operation. Inspection of the hoses and protection should be conducted regularly and documented as part of your plant safety programme.

Legislation: State Health & Safety Legislation & Regulation

References: AS2671, AS4024, ISO4413

Assessor Comments: Ensure that all hydraulic hoses are inspected by a competent person and any damaged hoses are replaced and secured correctly prior to

operation.



HIGH 22

MEDIUM 15

1 Week

16-Feb-21

Risk Treatment Required: Maintenance Manual

The manufacturer's maintenance manual(s) are not available for this item of plant

These manuals must be sourced and made freely available to all persons carrying out maintenance activities as a requirement of current legislation. If these manuals cannot be sourced, the maintenance manual(s) must be developed by a competent person, and then made available to all relevent persons.

Legislation: State Health & Safety Legislation & Regulation

References: Occupational Health & Safety Act & Regulations, Work Health & Safety Act & Regulations-



OPERATIONAL MALFUNCTION

HIGH 21

MEDIUM 15

1 Week

16-Feb-21

Risk Treatment Required: Service Records

Service and maintenance records are not available for this item of plant.

This risk assessment will form the basis of your records for this item of plant. Service and maintenance records must be developed and maintained as part of your plant safety management programme. This includes regular inspections re: the general condition of the item of plant including (but not limited to) tyre condition, oil levels and wear and tear on critical items such as brakes and steering, etc. All OEM prescribed, scheduled and non scheduled maintenance must also be documented as part of these records.

Legislation: State Health & Safety Legislation & Regulation

References: Occupational Health & Safety Act & Regulations, Work Health & Safety Act & Regulations-

SECTION 5 RISK TREATMENTS IN PLACE

This section of the report pertains to risk treatments currently in place on this item of plant. This section must be read in conjunction with the safety section of the manufacturers handbook. All operators must read and understand the entire contents of this section prior to operating this item of plant. These treatments or equivalent must remain in place at all times whilst this item of plant is in operation.

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating
OPERATION		
CRUSHING	HIGH 22	MEDIUM 15
Risk Treatment In Place: 3rd Arm Connection Point		
No load must be towed from any point above the centre line of the rear diff/axle. This includes the 3rd arm,	, the 3rd arm connection point ar	nd 3PL lifting arms.
References: AS/NZS2153		
BURNS	MEDIUM 12	MEDIUM 12
Risk Treatment In Place: Open Cabin		
Dust, exhaust fumes, chemical fumes, sunstroke and sunburn pose serious risk to the operator both short a	ind long term. The appropriate co	ontrols for all of these hazar

Dust, exhaust fumes, chemical fumes, sunstroke and sunburn pose serious risk to the operator both short and long term. The appropriate controls for all of these hazards must always be available whilst this item of plant is in operation. If these controls e.g. hats, sunscreen, dust masks etc are not available then operation of this item of plant must cease until these are made available to all operators.

References: ISO31000





Make International
Model 686
Type Tractor - Rigid

Serial Number Assessed By Date

	HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating						
DESIGN COMPLIANCE									
零	BURNS, STRIKING	HIGH 22	MEDIUM 15						

Risk Treatment In Place: Hydraulic Hoses

This item of plant has hydraulic hoses. These hoses must be inspected each day or before each use for wear and tear. If there are visible signs of wear immediate action must be taken to control the risk arising from this wear. These inspections must be documented.

Hydraulic fluid at high pressure can penetrate the skin, never use any part of your body to check for leaks. If oil penetrates the skin seek medical advice immediately. Always use a piece of cardboard or similar to check for suspected leaks.

Hydraulic pressure can be stored and is a hazard. Before disconnection or connection of hydraulic hoses complete the following steps -

- 1. Stop engine
- 2. Keep all bystanders clear of the work area
- 3. Refer to operators manual as to methods to release pressure
- 4. Wait 5 minutes

References: AS2671, AS4024



COLLISION, CRUSHING

CRITICAL 24

MEDIUM 15

Left/Right Brake Pedals

This item of plant fitted with individual left and right brake pedals, which have a sturdy, permanently attached connecting device which locks the brake pedals together to ensure that both pedals are depressed uniformly during straight line operation. This device must be present at all times during operation.



COLLISION, CRUSHING

CRITICAL 24

MEDIUM 15

Risk Treatment In Place: **Park Brake**

This item of plant is fitted with a fully functional park (hand) brake which meets the following requirements –

- Is separate to the service brakes
- 2. Has a device which maintains the brake in the on position until intentionally disengaged &
- 3. Requires at least two separate and distinct movements to disengage the park brake.

The park brake must be regularly inspected and tested. These inspections and tests must be documented as part of your plant safety programme.

References: ISO31000



COLLISION, POOR VISIBILITY

HIGH 22

MEDIUM 15

Risk Treatment In Place: **Machine Lights**

This item of plant is fitted with self contained lighting. All of these lights must be fully functional and serviceable whilst this item of plant is in operation in areas of reduced light. If any of these lights stop working the operation must cease immediately and the faulty light be repaired before operation can continue in the areas of reduced light.

References: AS/NZS2153



SLIPPING

MEDIUM 12

LOW 6

Risk Treatment In Place: Operator Work Area Access/Egress

Safe access and egress to the cabin/work area(s) must be maintained at all times whilst this item of plant is in operation. It must be non slip, free from damage, located at a height so as to not cause undue body stresses and strains with three points of contact available to personnel at all times.

All personnel must -

- 1. Always face the item of plant during access and egress.
- 2. Always maintain three points of contact during access and egress.
- 3. Never carry an object(s) in his/her hand(s) during access and egress.
- 4. Never jump off machine.

References: AS/NZS2153.3, AS1657, ISO4252



STRAINS

HIGH 19

LOW 5

Risk Treatment In Place: Controls Ergonomics

All controls including all levers, buttons, pedals, switches etc, are placed near the operator work position and are easy to reach and operate during the execution of the operator's normal duties. This applies for all persons within the 95th percentile of the normal population distribution.

References: AS/NZS4024.1901





International Model 686 Tractor - Rigid Serial Number Assessed By

HAZARD(S) Prelim. Risk Rating Residual Risk Rating DESIGN COMPLIANCE BURNS MEDIUM 9 LOW 5

Risk Treatment In Place: Exhaust

The engine exhaust on this item of plant is fitted with a guard to prevent injury to any person and control the risk of initiating a fire. It must be present and fully functional and serviceable at all times whilst this item of plant is in operation.

References: AS/NZS4024.1201



MEDIUM 9

LOW 4

Risk Treatment In Place: Operator Floor

All work area floors are non-slip and free from damage & debris.

Floor area must remain non-slip and free from damage & debris, including rubbish, tools and other items, at all times whilst this item of plant is in use.

References: AS/NZS2153, AS/NZS4024.1201



STRAINS

MEDIUM 9

LOW 1

Risk Treatment In Place: Operator Seat

The operator seat fitted to this item of plant must remain free from damage and tears, and be permanently and securely fitted at all times.

References: AS/NZS2153, AS/NZS4024.1401



INCORRECT OPERATION, INSTABILITY

CRITICAL 24

LOW 1

Risk Treatment In Place: Drawbar

The drawbar/tow hitch on this item of plant is below the centre line of the drive diff/axle. This must not be modified so that it is above the centre line of the drive diff/axle. No load must be towed from any point above the centre line of the drive diff/axle. This includes the 3rd arm and 3PL lifting arms.

References: AS/NZS2153

MAINTENANCE



COLLISION, INSTABILITY

HIGH 22

MEDIUM 15

Risk Treatment In Place: Tyres

The tyres and wheel components must be inspected as part of a "pre start" checklist. These inspections must be documented as part of your plant safety programme.

References: ISO31000



CURRENT OR PREVIOUS STRUCTURAL DAMAGE

CRITICAL 25

MEDIUM 15

Risk Treatment In Place: Structural Integrity

Regular checks for structural damage must be undertaken. Look for cracks in frames/chassis (current or repaired), bends or damage to structural components, etc.

References:



OPERATIONAL MALFUNCTION

HIGH 22

LOW 2

Risk Treatment In Place: Major Fluid Leaks

This item of plant must remain free from leaks at all times whilst in operation (this includes engine, transmission, cooling system, air, fuel, drive line, wheel hubs, steering and hydraulics). Development of a major leak will require this item of plant to be stood-down until repaired. Minor leaks detected must be repaired within 1-14 days.

References: ISO31000

SECTION 6 IMAGES AND NOTES







RISK MANAGEMENT REPORT

TYPE	Tractor - Rigid	Report Number	OSS 20210209-1448
MAKE	International	Date	9-Feb-2021
MODEL	686	Created By	Geoff Gleeson
SERIAL NUMBER	2510130A001246	Assessor	Geoff Gleeson
		Assist. Assessor(s)	
		Agent	Mannes Agencies
		Lot Number	06
		Location	Farm 4003
		Assessment Purpose	Sale
		State	NSW

PURCHASER ACKNOWLEDGEMENT

I the undersigned acknowledge that I have read and understand the risk management report described above. I also acknowledge that I have received a copy of this risk management report. I also acknowledge that I am authorised to sign on behalf of the purchaser.

Company Name
Position
Signature
Date
The manufacturer's operational & maintenance handbooks have been supplied, (circle one) YES NO (initial) Please transfer this assessment to my Plant Assessor membership as a (circle one) HIRE / PLANT IN USE assessment. My Plant Assessor username is



Name